

The following images from 4/14/2024 and 4/16/2024 illustrate the BSWCD's concerns about the SRWMD's failure to address the issue of trash and debris on the Edwards Bottomlands Project.

South side of Alligator Creek 4/14/2024





North side of Alligator Creek 4/16/2024



The trapped trash and debris slow flows in the secondary channel which can produce higher up stream peak water levels.